



MUGA Pitch and associated fencing.

Low height fencing.

Soft play repair to play area.

Tarmac replacement.

Site compound area: skips welfare etc.

Direct Access to rear playground from Horniman Drive. Note this is narrow and vehicular access is unlikely. We note a small digger may be able to access the site via this route.